

Renewed

S34 | S35

T30S R3W

Edward

1" Pipe at Sec cor. #72

12" Fir N74 $\frac{1}{2}$ E 45 $\frac{1}{2}$ DBT
Shows Scar

10" Fir NW 13" N 12 $\frac{1}{2}$ E 35 $\frac{1}{2}$
Shows good Scar

7" Laurel NW 10" N79 W 10 $\frac{1}{2}$
Scribed T30S R3W -

20" Laurel - S 8 W 22 $\frac{1}{2}$
"BT" in wood Bark Scribed

24" Laurel - S 36 E 18 $\frac{1}{2}$
"BT" in wood Bark Scribed

Renewed

Block side of Iron Pipe
Set Brass cap at Sec cor MKD
County Surveyors office

T30S

S34	S35	N
		S
		W
T31S		

1965

Bearing Trees,

24" Laurel S 36 E 18 $\frac{1}{2}$

Reblazed and Scribed T31S R3W S34S

As noted cor. lies on top of ridge
12-30-65

[Signature]

+ * #125 - T31-3
#188

C. S. File No. 577852/63-38

DIETZGEN NO. 388-6