

Renewal

S31 | S32

T305 R3W

Found

2 P.P. at Sec cor

29" D. Fir S 72 E 29' 2" off
Tree had been opened showing
faint scribing

14" Laurel N 88 E 19' 0"
Bark scribed

9" Laurel N 58 W 19' 0"
Bark scribed

14" Laurel S 17 W 26' 0"
Bark scribed T315 R3W 56 BT

Renewal

along side of Iron Pipe
Set Brass cap at Sec. cor MAD

County Surveyors Office

T305

S31 | S32 P

36 W

T315

19 66

Next Bearing Trees

Re scribed —

14" Laurel S 16 W 27' 2"
Scribed T305 R3W S31 25 BT

9" Laurel N 58 1/2 W 19' 0"
Scribed T315 R3W 56 25 BT

(Renewal # 82)

1-5-66
J. C. S.
T305

#125 - T31-3

+ X = 186

C. S. File No. 52/63-42

DIETZEN NO. 385-6