

Renewal

32 1/2
3/4

T 315 R 3W
T 323 R 3W

Found I Bolt at Sec corner - Plan #3-791-3

? 28" Fir NOW 42" N 72 E 30 E
Shows good Scar

15" Fir NOW 22" N 31 E W 63 E
Shows good Scars exped for
Scribble "92"

34" Fir NOW 38" S 34 W 34 E
Shows good Scar

Renewed

Set Brass cap at Sec cor MKP,
County Surveyors office

T 315

~~S 32 S 33~~
~~S 5 S 4~~

R
3
W

T 325

1966

New Bearing Tree:

8" D. Fir N 64 W 15 E

Scribed: T 315 R 3W S 32 CS BT

Renewal #3

1-6-66
G. M. S.
J. C. S.
T 315

T 315

C. S. File No. 52/63-46

DIETZGEN NO. 385-6

✱