

Renewal

S33 | S34

T30S R3W

Followed

Iron Pipe at sec. cor.

20" Fir Now 41" S71E 19⁰ BT
Shows good scars

30" Laurel Now 30" S34E 18⁰
Scribed "S 4" & Bark scribed "BT"

20" D. Fir Now 17" N88W 11⁰
Scribed "S 33" visible

15" D. Fir Now 18" S62W 15⁰
Bark scribed visible "3"

28" D. Fir Now 29" S84W 26⁰
Bark scribed
26 1/2 To Face

Renewed.

Along side of Iron Pipe
Set Brass cap at sec. cor. MKD.

County Surveyors office

T30S

S33 | S34 R

34 S

T31S

1966

New Bearing Tree.

Reblazed & scribed.

29" D. Fir S84W 27⁰E

Scribed T31S R3W S4 CS BT

18" D. Fir S62W 15⁰
Scribed S4 CS BT

(Renewal #23)

1-11-66

~~W.C. G.~~
W.C. G.

#126-313

#189

52/63.5

DIETZGEN NO. 385-6