

Renewed

515 | 514
522 | 523

T31S R3W

Found

Iron P.P. & Stone 174 Sec. cor.

20" Laurel DOWN N 73 1/2 E 57 1/2
OBT

28" P. Fir DOWN N 86 1/2 E 37 1/2
OBT

12" P. Fir DOWN S 36 1/2 E 30 1/2

24" cedar DOWN 30" S 7 1/2 W 23 1/2
Scribe visible "T31S R3W 52"

Renewed

Along side of Iron P.P.

Set Brass cap at sec cor. MCA

county surveyors office

T31S R3W

515 | 514
522 | 523

1966

DIETZEN NO. 385-6

New Bearing Trees:

8" Laurel NORTH 57 1/2
Scribed: T31S R3W S 15 CS BT

7" Laurel N 50 E 9 1/2
Scribed: T31S R3W S 19 CS BT

12" P. Fir S 67 E 28 1/2
Scribed: T31S R3W S 23 CS BT

(Renewed #33)

1-31-66
~~5/2/66~~
~~5/2/66~~
~~5/2/66~~

+ X#147

C. S. File No. 52/63-76