

Renewal
Found,

26/20
35/36

T31 S.R.3W1

18" Fir Now 15" N 28 E W 23 1/2
Scribe visible "T31"

28" F.E N 69° 20' E 31 1/2
No Trace of This Tree (78)

12" Fir S 2 1/2 W 10 1/2
No Trace of This Tree

30" Fir Now Stump S 75° 50' E 24 1/2
Scribe visible "536 CS BT"

No Trace of 1" Iron P.P.C

Renewal:

Set Brass cap at sec. cor. M.M.A.
County Surveyors office

T31 S R3W

526/525
535/536

1966

New Bearing Trees:

16" D. Fir N 26 E 30°
Scribed T31 S R3W S 25 CS BT

15" D. Fir S 68 W 25 1/2

Scribed T31 S R3W S 25 CS BT

This cor lies on edge of old
logging Rd.
Renewal # 27

A-A-66

C.S. File No. 52/63-89

DIETZGEN NO. 385-6

3199
*O