

Renewal

526/525

7315 RSW

Found

Stone at  $\frac{1}{4}$  cor.  $\frac{1}{4}$  N West face

12" Fir Now rotten stump S78W 14<sup>5</sup>

11" Fir Now 14' S12 $\frac{1}{2}$ E 12<sup>10</sup>

Has been opened for scribe. Face rotten but faint scribe marks visible

Renewed:

Set Brass cap at  $\frac{1}{4}$  sec cor NW $\frac{1}{4}$

county surveyors office

7315 RSW

$\frac{1}{4}$  526/525

1966

DIETZGEN NO. 385-6

New Bearing Trees:

13" Hemlock  
scribed  $\frac{1}{4}$  S 25<sup>5</sup> N40<sup>15</sup> E 23<sup>10</sup>  
CS BT

25" D. Fir  
scribed  $\frac{1}{4}$  S 26<sup>5</sup> N31<sup>15</sup> W 6<sup>10</sup>  
CS BT

1-13-66

*[Handwritten signature]*

© 184  
\*

C. S. File No. 52/63-96