

RENEW $\frac{1}{4}$ C, 512/57 T283

R/W R7 $\frac{1}{2}$ W

FOUND - BRASS CAP AT CORNER
SE BT IS OK SW BT NOW STUMP.

NEW BT.

12" R. FIR BEARS N 5° W 14.2'

SCRIBED $\frac{1}{4}$ S 12 CS BT

*

FILED

RECEIVED

MAY 4 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓ ✓ ✓
CS 52/79-6