

SECTION 1/4 COR 3 R2W T31S

FOUND - ORIG. 18" N.W. 24" PINE
N. COR. 24" PINE. PINE ONLY OPENED
SHOWS GOOD SCARS 1/4 S. W. 1/4
AND STUMP HOLE & REMAINS OF
AN OLD THAT CHECKS BEARING &
DIST. FOR ORIG. SUB BT

SET BRASS CAP AT COR. MKD.
COUNTY SURVEYORS OFFICE 1961
1/4 3/10 T31S R2W

NEW BT
9" R. FIR BEARS S 31° W 14.2'
SCRIBED 1/4 S 10 CS BT

JUNE 12 1961
J.T.D.
M. G.
P. D.

*

✓ 0

RENEW 8/17 CC T31S R2W

FOUND - BOTH B.T.S. RECORDED BY
MENSCH. EACH SHOWS GOOD SCARS
DISTS. CHECK OK SW BT SHOULD BE
S 59° W NOT S 52° W. BEARING TO
NW BT IS OK.

C.R. STONE NOT FOUND.

SET BRASS CAP AT COR. MKD
COUNTY SURVEYORS OFFICE 1961
38/517 T31S R2W CC

NEW B.T.S.
16" R. FIR BEARS N 76° W 72.7'
SCRIBED SF T31S R2W CS BT

36" CEDAR BEARS S 75° E 66'
SCRIBED CE S84S17 T31S R2W CS BT

*

✓ 0

C. S. File No. 52/8/10