

Renew Sec. Cor. $\frac{4}{9} \frac{3}{10}$ T245 R6W

Fd. O.B.T.s as follows -

Orig. 40" Now 48" Fir N. $86^{\circ}50'W$, 49.5 ft.

live - Bark scribe "T245 R6W" visible

O.B.T.s S.W. & S.E. Now sawed stumps

& N.E. O.B.T. Now Blow Down - 2 1/2 ft

Bearing & Dist. - 2nd cor. point set

1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1969 T245

$\frac{34}{59} \frac{33}{510}$ R6W" & MK. New B.T.s -

32" D. Fir. S. $36^{\circ}W$, 20° ft.

Mkd. "T245 R6W 59 CS BT"

22" D. Fir N. $50^{\circ}W$, $22^{\frac{1}{2}}$ ft.

Mkd. "T245 R6W 54 CS BT"

20" D. Fir N. $15^{\circ}E$, $38^{\frac{3}{4}}$ ft.

Mkd. "T245 R6W 53 CS BT"

No Trees available in Sec. 10

Due to Logging - good Blazed

line N. - cutting line S. & E.

Oct. 6, 1969

VRT.
J.G.H.
V.D.P.

V.R. Tray

Oct.
B.W.B.

C.S. File No. 52/102-5