

Renewal

$\frac{54}{59}$

T295 R6W

Found:

48" D.F.V. Now stump S17 $\frac{1}{2}$ E 22 $\frac{1}{2}$   
old Bart scribe visible  $\frac{1}{4}$ S BT

65" D.F.V. Now 66" N18 $\frac{1}{2}$ E 16 $\frac{5}{8}$   
Badly Burnt Face Part of "B" visible

Renewal

set Brass cap at  $\frac{1}{4}$  cor NW/4

County Surveyors office

T295 R6W

$\frac{1}{4}$   $\frac{54}{59}$   
1972

New Bearing Trees

6" Cedar S49 E 20 $\frac{1}{2}$   
Scribed  $\frac{1}{4}$  S9 CS BT  
Note: Face Bearing & dist.

16" D.F.V. N 65 W 33 $\frac{1}{2}$   
Scribed  $\frac{1}{4}$  S4 CS BT

10-2-72

*[Handwritten signature]*

O.K. *[Handwritten initials]*

NO

#102 ✓

S. File No. 52/102

DIETZGEN NO. 385-6