

REN.

T23SR6W

COR.
SECS.27/26
34/35

FD. G. L. O. BRASS CAP & NAINES'

"T" IRON AT COR.

FD. 29" FIR N47 $\frac{1}{4}$ °W 208 $\frac{1}{2}$ FT. SCRIBING
VISIBLE. TREE ALIVE & IN GOOD CONDITION.FD. 25" MAPLE N87°E 141 $\frac{1}{2}$ FT.
SCRIBING VISIBLE. TREE ALIVE & IN GOOD
CONDITION.FD. 46" CEDAR S34 $\frac{3}{4}$ °W 91 $\frac{1}{2}$ FT.
TREE STANDING BUT DEAD. MARKS ALL
BURNED OFF.FD. 30" CEDAR S50°E 32 $\frac{3}{4}$ FT. UPROOTED
& DOWN. MARKS ALL BURNED OFF.PART OF OLD MAPLE STUB S80°E 10 $\frac{1}{2}$ FT
STILL STANDING, BUT DEAD & BURNED.
NO MARKINGS LEFT.

BLAZE & SCRIBE 2 NEW TREES:

34" MAPLE S89°W 128 $\frac{3}{8}$ FT

MKD. "T23SR6W S34 CS BT"

34" RED CEDAR (TOP BROKEN OUT) S30°E
92 $\frac{3}{4}$ FT. MKD. "T23SR6W S35 CS BT"

NOV. 2, 1962

Milo E. Coffey

M.G.
V.T.
M.S.