

RENEW 18/17  
19/20

T 295 R 3 W

FOUND - ALL BTS AS RECORDED  
BY BBI EXCEPT SUGAR PINE  
AND W NOT 270° AS 3 CHAIRS  
GOOD SUGAR S E BT DOWN. S W  
SOME BTS OK SHOW GOOD  
SCRIBING (BARK). WE ALSO FIND  
A "X" SCRIBED STAKE ON  
GROUND AT CORNER AND 1 1/2" I.D.  
AT CORNER.

SET BRASS CAP AT CORNER  
MARK COUNTY SURVEYORS  
OFFICE 1962. 518/517 T 295 R 3 W

NOTE: 519/520  
BBI BTS CHECK FOR DISTANCES ON AS  
MEASURED TO FACES.

NEW BTS.  
2" CEDAR BEARS N 26° W 125  
SCRIBED 5 18 T 295 R 3 W CS BT.

10" R. FIR BEARS S 20° E 579  
SCRIBED 5 20 T 295 R 3 W CS BT

RENEW 1/4 COR. 18/17 T 295 R 3 W

FOUND - BOTH BTS. # 1" PAT CORE  
AS RECORDED BY MARKHAMS.  
WE ALSO FIND BOTH ORIG. BTS  
WITH SCRIBING AS RECORDED.  
EXCEPT NOW 30" LAUREL O.B. BT  
SHOULD BE 20" W 170° NOT 160° W  
9/6" THIS TREE MAY HAVE SLID  
DOWN HILL.

NOTE - MARKHAMS 542° E BT.  
DIST. IS 19.5'

NEW BT.  
7" CEDAR BEARS S 11° W 176  
SCRIBED 1/4 5 10 CS BT.

VAR 20 1/2  
C.S. No. 52/26-70  
OCT 26-1962  
U.S.  
B.S.

DIETZEN NO. 385-6