

RENEW  $\frac{5}{8}$  T 295 R 9 W

Cor. #126

FOUND - 2 1/2" I.P. AT CORNER  
AND ALL BTS. RECORDED BY  
MARKHAM N.E. BT NOW  
DOWN

NEW BT

7" K-FIR BEARS N 56° E 26.8

DESCRIBED  $\frac{5}{8}$  CS BT ~~2~~  
+ \* ✓

Cor. #11

RENEW  $\frac{1}{4}$  COR  $\frac{5}{4}$  T 295 R 9 W

FOUND - 1" I.P. AT COR.  $\frac{1}{4}$

BOTH BTS. AS RECORDED BY

FREAR. ORIG. 12" NOW 30" W. FIR

N 10° W NOT N 20° W 211 SHOWS SCRIBE

MKS. ORIG. 40" NOW 44" R. FIR 579° E

NOT 589° E. 218 SHOWS BARK SCRIBING

SET BRASS CAP AT COR. MKD. COUNTY

SURVEYORS OFFICE 1963  $\frac{1}{4}$  55/54 T 295 R 9 W

NEW BT:

RESCRIBE NOW 30" W. FIR N 10° W

22°  $\frac{1}{4}$  55 CS BT

+ \* 0 CS 52/126 - 118