

RENEW $\frac{1}{4}$ COR 910 T 295 R 9 W
FOUNDED - $1\frac{1}{4}$ " I.P. AT COR $\frac{1}{4}$
BOTH BTS AS RECORDED BY
MARKHAM.

WE RESURFACE (WOOD) 20" PINE
585' W COR SCRIBED $\frac{1}{4}$ 59 CS BT

APRIL 30 - 1963

MID
B.S.

~~10~~ O.K. W B

RENEW SOUTH $\frac{1}{4}$ 532 T 295 R 9 W
FD $3\frac{1}{4}$ " I.P. AT COR $\frac{1}{4}$ BOTH BTS
RECORDED BY MARKHAM NOW
DOWN WE ALSO FIND BOTH ORIG.
BTS NW BT DOWN.

NEW BTS.

9" R. FIR BEARS N 56° W 7.9
SCRIBED $\frac{1}{4}$ 532

12" R. FIR BEARS N 83° E 2.5
SCRIBED $\frac{1}{4}$ 532 CS BT

DIETZEN NO. 388-6

3

C.S. File No. 52/126 130