

MAY 16, 1963

RENEW

T295 R4W

MD
B.S.

~~22~~
~~27~~

FOUND

BRASS CAP

20" FIR

S 65 E 35 S

OK

30" FIR

N 10 W 62 S

STUMP

32" LA

N 80'

DOWN

NBT 23" LA

N 37 W 46 S

~~22~~ ✓

RENEW

~~22~~
~~34~~

FOUND

T295 R4W

BRASS CAP

10" FIR

N 45 E 40 S

OK

12" FIR

N 56 W 26 S

OK

30" CEDAR

S 52 W 35 S

DOWN

NBT 5" FIR

S 49 W 25 S

SCRIBED 4.5 34 CS RT

~~22~~ ✓

DIETZGEN NO. 385-6