

T 23 S R 3 W

Reset S.W. cor. of W. M. Whitney Don. T 21 S.R. 3 W. ✓
Old B.T. oak 18" S 60° E. 24 lks. standing but dead and rotten. Found figures in rotten wood. Old B.T. fir 36 N 22° E. 62 lks. standing, nearly dead and rotten at butt.

Set stone 4x6x10

Fir 20 N 77° W 64 lks.

Fir 20 N 89° E 62 lks.

John Woodard present

July 24, 1903

Harvey Taylor Surveyor

Reset 1/4 sec. cor. on 5th Stand. Parallel South bdy. ✓
sec. 31 T 22 S.R. 3 W. Found old post gone
Old B.T. fir 48" South 14 lks. standing figures all gone on account of having been put in bark. Old B.T. decar 30 ins. N 35° E. 30 lks. standing spot rotten and parts of 1/4 S. barely visible. Set new yew post.

Yew 12" S. 67° W. 25 lks.

Cedar 30" S. 83° E. 63 lks.

Wm. Jones and H. Combs present

Jan. 9, 1905

#16

Reset N.W. cor. of M.E. Anderson Don. Cl. 40 T 22 S.R. 3 W. ✓

Found old post gone, Old B.T. and oak 12" S 20° E. 49 lks down and rotten. Figures in rotten wood.

Set new fir post on N. side of a stone 10x12x14"

Fir 20 N. 31 1/2° W. 130 lks.

Fir 12 N. 31 1/2° E. 156 lks. Marked C.S.B.T.

L. Geer and Geo. Southerland present

Jun. 20, 1905

Dec. 1960
Reset cor. with a steering shaft 36" long in a mound of rock. COUNTY SURPTA.

Harvey Taylor Surveyor

Reset S. E. cor. of sec 32 T 22 S.R. 3 W.

Found old post gone. Old B.T. Fir 30" N 75° W 34 lks. cut down

Figure B T in stump. Old B.T. cedar N 33° E burned down no figures

Set new yew post

Yew 10 S 40° E 66 lks. Fir 36 N 80° E 48 lks.

H. A. Powell and H. Combs present

Feb. 15, 1905

~~17~~

1055 Fern

Cor #17

30 copies