

Re-establishment of the Sec. Cor. for Secs. 5 & 6, T23S, R3W, WM
and " " " Secs. 31 & 32, T22S, R3W

#17

Corner for Secs. 5 & 6, T23S, R3W

Chopped out SW bearing tree marked by Harvey Taylor, Feb. 15, 1905

Douglas Fir 16" diam. when scribed, now 26" in diam. brs. S 55°W 35.6 ft.

Fir 14" diam. when scribed, felled; stump now 26" diam. brs. N 73°E 51.5 ft.;
scribing "C.S." in standing tree plainly visible.

Set 2" iron pipe 4' long in ground, leaving 3" above ground.

J. F. Woodard present.
Dec. 9, 1953

Gilbert A. Gardner, Surveyor

Corner for Secs. 31 & 32, T22S, R3W

Found stump of NE BT marked by Harvey Taylor, Feb. 15, 1905, which brs. N 64°E
49.5 ft.; a portion of scribing barely visible where someone had cut into the stump

Stump of 14" Fir S 58°W 11.2 ft. standing but badly burned, obliterating all marks

Set 2" iron pipe 48" long in ground, leaving 3" above ground.

J. F. Woodard present
Dec. 9, 1953

Gilbert A. Gardner, Surveyor

Replacement of $\frac{1}{4}$ Corner between Secs. 9 & 10,
T22S, R3W, WM

At point 2654.3 feet South (variation 19°30' East) find stake from which
original Hemlock bearing tree bears South 80° West 11.2 feet;

At this point, set new Cedar stake 4"x4", 4 ft. long, marked "1/4 S", from
which a new bearing tree, 20" Hemlock, marked "1/4 S" bears South 51° East 30.0 ft.

From this $\frac{1}{4}$ corner, the $\frac{1}{4}$ corner between Sections 10 & 11, said Township and Range,
bears South 89°05' East 5179.9 ft.

Nov. 9, 1953.
Present: Robert Barta
Don Walker

/s/ Gilbert A. Gardner

CS 53/1-16