

FD,

T 235 R 4 W

1/4 S 19
S 30

RENEWAL
NOT
RECORDED

FD, STEEL SRAFT, (1 1/2" DIAM.),
9" ABOVE GROUND. - MHD. "A" ON TOP.

A 28" DOUG. FIR BEARS S 88° W
16 1/2 FT. - SCRIBING "1/4" VISIBLE ON
BADLY BURNED FACE. - NOT ORIG TREE;

A BADLY BURNED & HOLLOW YEW
STUMP - NO MARKINGS - BEARS
APPROX. BEARING & DIST FOR ORIG.
N.W. B.T.

WE HAVE NO RECORD OF ANY
RENEWAL FOR THIS COR. - A YELLOW
TAG ON THE FIR HAS THE NAME
"L.J. MARTIN" DATED "10-22-54"
DID NOT RENEW COR.

MAY 17, 1963

M.G.
V.T.
M.S.

FILED
RECEIVED

MAY 16 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

SEE OVER & S. File No. 53/9-6
4

Section 18 Twp 23 S Rge 46 W Date: 5/13/63

How was corner identified? 1/8" dia. iron stake

marked (4)

Condition of corner: Iron stake OK B.T.'s

POOR.

Best route to reach corner: Interstate #5, Hwy 99

Pleasant Valley road, up Red Hill to headwaters of

Adams Other Remarks:

DID NOT RENEW
 RENEWAL NOT
 RECORDED.
 NOT ENOUGH
 EVIDENCE OF ORIG.
 COR. LEFT TO
 GIBB & GIBB
 RENEW



Quadrant	NE	NW	SE	SW
Species & Size	30" D. Fir			
Dist. & Bearing	5880, 16.6'			
Condition of Scribe	poor			
Original or Resurvey	?			
Appearance of B.T.	Fair			
Tags, Marks, etc.	BLM Lug.			

CS 5319-6

Signed B