

REN. T 24 S R 4 W  $\frac{1}{4}$  S 27

S 34

FD. LAUREL STOOD OF YOUNG

SHOOTS WITH LARGE STUMP HOLE IN CENTER -  
FRAGMENTS OF ROTTEN LAUREL WOOD ON  
GROUND. - FD. OLD AXE MKS. IN WOOD. - ALSO  
A FAINT, ILLEGIBLE, PORTION OF REVERSE  
SCRIBING ON BADLY ROTTED FACE. - LAUREL  
S 76° W 20 $\frac{1}{2}$  FT.

FD. STUMP HOLE ONLY, N 20° E 59 $\frac{1}{2}$  FT.  
NO TRACE OF TREE REMAINS.

AT COR. SET IRON PIPE WITH BRASS  
CAP MKD. "COUNTY SURVEYOR'S OFFICE  
1963 T 24 S R 4 W  $\frac{1}{4}$  S 27"  
S 34

BLAZE & SCRIBE NEW TREES:

11" DOUG. FIR N 31° E 21 $\frac{1}{2}$  FT.

MKD. "  $\frac{1}{4}$  S 27 CS BT "

6" DOUG. FIR S 35° W 15 $\frac{1}{2}$  FT.

MKD. "  $\frac{1}{4}$  S 34 CS BT "

COR. LIES ON WEST SLOPE APPROX.  
50 FT. WEST OF TOP OF SPUR SLOPING  
N.W.

MAY 8, 1963

M.G.

V.T.

M.S.

Milo E. Godfrey

\* $\checkmark$  10

C. S. File No. 5319-62