

REN.

T 24 S R 4 W

ORIG. $\frac{S12}{S13}$
C.C.

(ON W. LINE SEC. 7 T 24 S R 3 W)

FD. CEDAR TREE (NOW 34" DIAM.)

S 73° W 21 $\frac{8}{2}$ FT. - PREVIOUSLY
OPENED - OLD SCRIBING "13 BT"
VISIBLE ON OLD FACE. - TREE STILL
ALIVE, BUT TOP BROKEN OUT APPROX.
40 FT. ABOVE GROUND - NEWER SCRIBING
VISIBLE "AM BT"

FD. FIR TREE (NOW 32" DIAM.)

N 6° W 31 $\frac{0}{2}$ FT. - HAS BEEN OPENED
PREVIOUSLY, BUT SCAR NEARLY
HEALED SHUT - NO SCRIBING VISIBLE -
NEWER BLAZE BELOW - ALSO HEALED
OVER.AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1963 T 24 S R 4 W ORIG.
CC $\frac{S12}{S13}$ "FROM THIS COR., BRASS CAP
SET BY PRICE FOR CC $\frac{S12}{S13}$
BEARS WEST 41 $\frac{6}{2}$ FT. -
(63 LBS. INSTEAD OF 62 LBS.)I DID NOT MARK ANY NEW
TREES.

JUNE 18, 1963

M.G.

V.T.

M.S.

Milo E. Godfrey

(SEE OVER)

C.S. File No. 53/9-106

FX ✓

FD. O.K.

$\frac{1}{4}$ $\frac{51}{512}$ T24SR4W

THE COR. TREE & BOTH FIR
B.T.'S ALIVE & STANDING - GOOD CONDITION
THE ORIG. CEDAR B.T. STILL ALIVE
BUT IN POOR CONDITION - SCRIBING
VISIBLE.