

REN. TWP'S 23424S R4W COR.  $\frac{35}{21}$   $\frac{36}{1}$   
SECS.

AT COR. FD. G.L.D. BRASS CAP  
IN MOUND OF ROCKS. - (1957 SURVEY)

FD. 26" FIR S28°W 48  $\frac{3}{4}$  FT. -  
SHOWS GOOD SCARS. - ALIVE & IN  
GOOD CONDITION.

FD. 7" WHITE FIR N46°E 31  $\frac{0}{10}$  FT.  
ALIVE & IN GOOD CONDITION - SCARS.

THE 45" CEDAR N88°W 38  $\frac{2}{4}$  FT.  
HAS DEAD TOP & APPEARS TO BE  
DYING.

THE 14" CEDAR S48  $\frac{1}{2}$ °E 49  $\frac{1}{2}$  FT.  
IS BROKEN OFF APPROX 15 FT.  
ABOVE GROUND

THE CHINGUAPIN STUMP TO THE  
N.E. IS STILL IN EXISTENCE.

THE FIR SNA& TO THE S.E. STILL  
STANDS. - OLD SCRIBING VISIBLE.

BLAZE & SCRIBE 2 NEW  
TREES:

7" WHITE FIR S11°E 17  $\frac{8}{10}$  FT.  
MKD. "T 24SR4W S1 CSBT"

8" RED CEDAR N32  $\frac{1}{2}$ °W 43  $\frac{8}{10}$  FT.  
MKD. "T 23SR4W S35 CS BT"

JUNE 20, 1963

M.G.

M.S.

C.S. File No.

53/9-108

+ X ✓ *M.G.*

*E. G. Galt*