

REN.

T 23SR4W

COR.

29	28
32	33

FD. CEDAR TREE (NOW 42" DIAM.)

S 28° E 240⁷ FT. SCRIBING VISIBLE
IN PREVIOUSLY OPENED SCAR "3 R4W
BT" - TREE ALIVE & IN GOOD CONDITION.

FD. WHITE OAK (NOW 30" DIAM.)

N 9° E 90⁰ FT. - 2 GOOD SCARS !
VISIBLE - DID NOT OPEN. - TREE
ALIVE & IN GOOD CONDITION.DID NOT FIND IRON BAR SET BY
EPPSTEIN.AT COR. SET IRON PIPE WITH BRASS
CAP MKD. "COUNTY SURVEYOR'S OFFICE
1963 T 23SR4W

S 29	S 18
S 32	S 33

"

BLAZE & SCRIBE ONE NEW TREE;

13" ASH S 28° W 18³ FT.

MKD. "T 23SR4W S 32 CS BT"

NO TREES AVAILABLE TO NW.

COR. FALLS IN FENCE COR. - FENCE
NORTH, SOUTH, & EAST FROM COR.

MAR. 21, 1963

Milo E. Godfrey

M.G.

Y.T.

M.S.

TXV0

C. S. File No.

53/9-125

Section 29-22-33 Twp 23 S Rge 4 W Date: March 4, 1963

How was corner identified? Found 2 B.T.'s Standing

RENEWED
 MAR 21 1963
 MR. J. M. E. Godeffroy

Condition of corner: Metal Detector Showed No

Evidence of 7" x 30" Iron Bar Set in 1932

Best route to reach corner: Go South on Elk Head Rd. Approx
Power Line Crosses Rd.

1/2 Miles From Howard Rd. intersect. 700' East To Cor.

Other Remarks:

Renewal Notes in
C.S. OFFICE omits E
From N 9° E 90.0'

Quadrant	NE	NW	SE	SW
Species & Size	18" W.O.		30" Cedar	
Dist. & Bearing	N 9° E 90.0'		S 28° E 240.7'	
Condition of Scribe	Not Chipped out		Visible	
Original or Resurvey	Resurvey		Resurvey	
Appearance of B.T.	Good		Good	
Tags, Marks, etc.				

John Godeffroy
 Signed: