

RENEW 1/6 T305

R6W R5W

FOUND 1" B. OAK 12" UNDER SURFACE 20' W. OAK S 35° W 2686 SHOWS GOOD SCAR 20' S. O. N 62° W 3145 SHOWS GOOD SCAR 16" B. OAK S 10° E 2402 SHOWS GOOD SCRIBING.

SEE COR. # 39, # 28

NEW BT.

11" B. OAK BEARS S 29° E 2137 SCRIBED S 7 T300 R6W C 3 BT

✓ 1/2 21-1963 J. B. M. D. J. H.

RENEW 1/12 T305

R6W R5W

FOUND 1 1/4 AXLE AT COR. 24' UNDER SURFACE NO TRACE OF BT FOUND CHECKS BEARING # DIST FROM 16 N 10° W 2625 Pen # 19, T30-6W.

SET 3/4" I.R. ALONGSIDE AXLE 4 12" UNDER.

NEW BTS.

8" W. OAK BEARS S 59° W 1436 SCRIBED S 12 T300 R6W C 3 BT

12" B. OAK BEARS N 65° W 1068 SCRIBED S 1 T300 R6W C 3 BT

NOTE SET 3/4" I.R. UNDER FIELD

FENCE N 65° W 496'

C. S. File No. 53/26-24

DIETZEN NO. 385-6