

RENEW $\frac{26}{35} \frac{25}{36}$

T 30 S R 5 W

FOUND - TWO BTS. PER COR. #
27 20" FIR STUMP S 65° E 68°
WE. OPEN & FIND GOOD SCRIBING.
NW BT NEW STUMP DOWN & OUT
OF POSITION. SHOWS SCRIBING.
NO OTHER BTS FOUND.

NOTE - COR. IS UNDER 320 W. FENCE
AXLE SET AT COR. NOT FOUND.

SET BRASS CAP AT CORNER
MND. COUNTY SURVEYORS OFFICE
1963 $\frac{526}{525}$ T 30 S R 5 W
535 536

NEW BTS.

18" B. OAK BEARS N 23° W 33.5'
SCRIBED 526 T 30 S R 5 W C 5 BT

16" W. OAK BEARS N 31° E 68°
SCRIBED 536 T 30 S R 5 W C 5 BT

12" R. FIR BEARS S 13° W 57.8'
SCRIBED 535 T 30 S R 5 W C 5 BT

6" ALDER BEARS S 32° E 18.9'
SCRIBED 536 C 5 BT

NOV. 12 - 1963

H. J. I.
H. J. I.

DIETZGEN NO. 385-6

#101

53/26-40