

REN T 27 S R 4 W.  $\frac{1}{4}$  S  $\frac{1}{36}$

FD. DOGWOOD - BADLY ROTTED -  
N  $85^{\circ}$  W  $5\frac{3}{4}$  FT. - OPENED & FD.  
FRAGMENTS OF REVERSE SCRIBING  
ON OVERGROWTH OF OLD FACE.

FD. PORTION OF STUMP & ROOTS  
(BADLY ROTTED) OF CEDAR S  $81^{\circ}$  E  
 $\frac{1}{2}$  FT.

AT COR. SET IRON PIPE WITH  
BRASS CAP MKD. "COUNTY SURVEYOR'S  
OFFICE 1964 T 27 S R 4 W  $\frac{1}{4}$  S  $\frac{1}{36}$ "

BLAZE & SCRIBE NEW TREES:  
25" HEMLOCK S  $74^{\circ}$  W  $28\frac{1}{2}$  FT.  
MKD. " $\frac{1}{4}$  S 35 CS BT"

53" DOUG. FIR. N  $56^{\circ}$  E  $24\frac{1}{2}$  FT.  
MKD. " $\frac{1}{4}$  S 36 CS BT"

COR. LIES ON VERY STEEP  
NORTH SLOPE APPROX. 1 CHAIN  
SOUTH OF SMALL STREAM RUNNING  
WEST.

APRIL 20, 1964

Milo E. Godfrey

M.G.  
W.S.  
M.D.  
M.S.

+XV6

(SEE OVER)  
NF

C.S. No. 53/3347