

RENEW $\frac{1}{4}$ COR. 28 T 27 S R 5 W
 $\frac{33}{33}$

FOUND - BOTH ORIG. BTS. ORIG.

12" NOW 20' B. OAK S 33° E

NOT S 23° E 9.2 SHOWS GOOD
SCRIBE MARKS. ORIG. 12" NOW

24" B. OAK N 13° E 9.2 SHOWS

GOOD SCARS EACH BT; HAS
RATTLED CENTER.

SET BRASS CAP AT CORNER

MND. COUNTY SURVEYORS OFFICE

1963 $\frac{1}{4}$ S 28 T 27 S R 5 W
 $\frac{33}{33}$

NOTE - COR. AT N. S. FENCE

NEW BTS.

14" R. FIR BEARS S 68° W 39.5'

SCRIBED $\frac{1}{4}$ S 33 C S BT

12" B. OAK BEARS N 75° W 41.5'

SCRIBED $\frac{1}{4}$ S 28 C S BT

DEC 9 1963

J. B.

J. H.

DIETZGEN NO. 385-6

X/O

C. S. File No. 53/3814