

Reviewed:

S 9 1/2°
S 14 1/2° S 15°

T 275 R 5 W

Found:

Steel Pipe at Sec Coy ^{Run # 64}
geom affected: Flush with ground,

14" B. Oak Now 35" N 24 1/2° W 64°
shows very slight scar.

16" B. Oak Now Down N 34 1/2° E 89°

20" B. Oak Now Down S 4 1/2° W 342°

All O. B. T's

300 L
310

Reviewed:

New Bearing trees

12" W. Oak N 88° E 14°
Scribed T 275 R 5 W S 10 C S B T

11" Laurel S 7° E 48°
Scribed T 275 R 5 W S 15 C S B T

Re-blazed & Re-scribed

35" B. Oak N 24 1/2° W 64°
Scribed T 275 R 5 W S 9 C S B T

This cor lies due north of
Fence cor 45 FT.

FILED

RECEIVED

3-24-66

MAR 25 1966

J. M. G.
D. C. G.
S. J. G.

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

* #109 O. N. J. B.

C. S. File No. 53/38-32

DIETZGEN NO. 385-6