

R6w 51 | 56 R5w

Review Sec. Cor, 512 | 57 T275 R's 5' & 6w.

Fd. 5/8" Iron Bolt, 8" below surface of ground & B.T.s as follows - (see Rev. #38)

12" Now 20" W, 02K N. 40° E. 75 ± ft.

2 live - shows good scars - we do not open.

20" Now 26" W, 07K N. 46° W. 132 ± ft

2 live - shows good upper scar - Lower Blaze shows "BT" scribe. Set in place

of Bolt 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYOR'S OFFICE

1967 T275 R6w

51	56
512	57

 R5w"

Flush with ground - Reset Bolt along side. Also set 6 ± ft steel

fence post 2 ± ft. South of cor.

This cor. lies 75 ± ft. South of Newton Creek in open field.

Sept 1, 1967

U.R.T.
J.H.
D.W.

U.R. Tracy

#135-T27-b

#116

C.S. File No. 53 / 38-35