

RENEW  $\frac{1}{4}$  COR 27/26 T30S R6W

FOUND - BTS AS RECORDED COR. #55. WE DO NOT FIND I.R. AT CORNER.

SET BRASS CAP AT CORNER

MKD. COUNTY SURVEYORS OFFICE

1969  $\frac{1}{4}$  S 27/26 T30S R6W

NOTE - COR IS OLD FENCE LINE BUT IS 10' WEST OF EXISTING FENCE

+\*<sup>o</sup>

RENEW NW COR. DLC. #2

T30S R6W

FOUND -  $\frac{1}{2}$  I.R. AT COR ~~#~~ BOTH

BTS SEE COR #56

SET BRASS CAP AT CORNER MKD.

COUNTY SURVEYORS OFFICE 1969

NW DLC #2 T 30 S R 6 W

NOTE: COR. IS IN N.S. FENCE LINE

NEW BT.

FILED 20" DOUBLE CEDAR BEARS N 9° E

RECEIVED 27°  
SCRIBED NW 42 CS BT

+\*

JAN 10 1984

JAN 8 - 1969

J. B.

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

M.D.  
O.S. FILE NO. 53/100

DIETZEN NO. 3885-6