

REN. T 30 S R 6 W $\frac{1}{4}$ $\frac{S 8}{S 17}$ OK

FD. DOUG. FIR STUMP (NOT PINE)

(NOW 30" DIAM.) S 50° E 19⁸ FT. - OLD

SCRIBING FD. "BT" - RING COUNT

100 YRS. IN. - (NOTES CALL FOR 10" PINE
S 40° E 13² FT.)

FD. DOUG. FIR SNAG (NOT PINE)

N 70° E 29² FT. - OLD SCRIBING
VISIBLE "1/4 S" - (NOTES CALL FOR
14" PINE N 80° E 29² FT.)

WHILE BEARINGS DO NOT CHECK
NOTES, THE SUBTENDED ANGLE CHECKS -
RING COUNT PROVES THEY WERE SCRIBED
APPROX. 100 YRS. AGO - I BELIEVE AN
ERROR OF 10 LKS. WAS MADE IN DIST.
TO S.E. TREE, - AT INTERSECTION OF
BOTH RECORD DISTANCES, NEITHER BEARING
NOR ANGLE BET. THEM CHECK.

AT COR. SET IRON PIPE WITH
BRASS CAP MKD. "COUNTY SURVEYOR'S
OFFICE 1964 T 30 S R 6 W $\frac{1}{4}$ $\frac{S 8}{S 17}$ "
BLAZE & SCRIBE NEW TREES!

27" DOUG. FIR S 35° E 25⁸ FT.

MKD. "1/4 S 17 CS BT"

7" INCENSE CEDAR N 7¹/₂° E 30⁴ FT.

MKD. "1/4 S 8 CS BT"

BRASS CAP SET BY MARKHAM

FOR THIS COR. BEARS S 58° E 68⁰ FT.

MARKHAM'S CAP SET AT POSITION OF COR.

SET BY ROYER WHEN HE WAS C.D.

COR. IS ON STEEP NORTH SLOPE.

C. S. File No. 53140-56

CHECK FORMER
REVENUES

JULY 1, 1964

M.S.
M.B.
M.S.

