

Renovals

16/15
21/22

T 303 P 6 W

Found:

orig Tree:

6" B. Oak NW 1/4" 328 W 1202
opened for suicide "21"

No TRACE OF OTHER ORIG. BT'S
FOUND.

Renovals

Set Brass cap at Sec cov M&D,
County Surveyors office

T 305 P 6 W

516/515
521/522

1970

DIETZGEN NO. 385-6

New Bearing Traces

7" W. Oak N 9 W 515
scribed T 305 P 6 W 516 C.S. BT

19" W. Oak N 70 E 365
scribed T 305 P 6 W 515 C.S. BT

10" W. Oak S 77 1/2 W 122
scribed T 305 P 6 W 521 C.S. BT

8" P. Oak S 70 E 21
scribed T 305 P 6 W 522 C.S. BT

SKIDING

Note: ~~Tree~~ from Renovals # Bl-162
Destroyed + Iron Pipe Removed.

OVERT

12-B-70

#208

NO. 61111

53/40

11/20
103/03

NOTE -

THE ASH USED BY J.H. MARKHAM
TO LOCATE THE SEC. COR 16/15
21/22
WAS NOT OF RECORD, IT
DOES SHOW OLD AXE, YVORK
AND SCRIBE MARKS. (VERY
OLD).

THE BLACK OAK USED ON
THIS DATE, TO MONUMENT THE
CORNER CHECKS RECORD IN ALL
RESPECTS. ALSO TIE FROM
OLD NICKEL MT. ROAD ^{TRAVERS} CHECKS
WITHIN A FEW FEET OF PRESENT
CORNER LOCATION.

J.W.D.
12-8-70

Tic from Brass cap to
Iron Pipe (Renewal # 81)

