

Revised # 27

$\frac{29}{25}$

T303 R6W

Found:

12" P. Fir New stump S51W 17' $\frac{1}{4}$
opened for Scribe "BT"

12" B. Oak New 23' N89W 26' $\frac{1}{4}$
Shows scars

No trace of 1" Iron Pipe falls
in skid Rd.

Revised 1

Set Brass cap at $\frac{1}{4}$ cor M&R
county surveyors office

T303 R6W

$\frac{1}{4} \frac{529}{525}$

1970

New Bearing Tree

8" P. Fir S20E 11' $\frac{1}{4}$
scribed $\frac{1}{4}$ S 25' 23' B T $\frac{1}{4}$

11-25-70

~~9 1/2~~
~~11 3/4~~
~~4 1/2~~

G.M.
T. W. P.

#207

U. S. FILE NO. 53/40'

DIETZGEN NO. 385-6

101