

Renewal #13 $\frac{20}{29} | \frac{21}{28}$ T305 B6W

Found:

12" D. Fir NW/1 stump SIZE 22°
 No scribing found on face (burnt)

8" Laurel NW/1 N18E 18°
 No scribing on face

orig Laurel Burnt out S88E 49.5

No Trace of NW 13T.

Also Brass cap has been broken off
 not found found concrete with pipe in
 it probably was brass cap. Cement has
 been moved from logging operations.

Renewal

Set Brass cap at Sec cor NW/4
 county Surveyors office

T303 N6W

$\frac{520}{529} | \frac{521}{528}$

1969

Reblazed & No scribe

8" Laurel N18E 18°
 Scribed 521 CS 8T

New Bearing Tree

13" Pine N27W 105.2
 Scribed T305 B6W 520 CS 8T

No other Trees Available.

10-9-69

J.M.D.
 J.W.B.

O.K.
 J.W.B.

#204

C. S. File No. 53/40-107

DIETZEN NO. 385-6