

Renew S.E. D.L.C. #49 T255 R4W

Fd at COR. STUMPS of BT's Recorded in
Renewal #15, also a $3\frac{1}{4}$ " x 22" I.P. set
loosely 12" in ground at COR pt.

a 15" now 24" cedar N. $74\frac{1}{2}$ ° W. 37° ft.

"5" visible on broken stump & "C 49" scribe
visible on chopped out log lying nearby.

8" now 22" cedar N. $43\frac{1}{2}$ ° E. 44° ft.

stump 18" high - we open & find "BT" scribe.

set 1" I.P. & BRASS COP MKd "COUNTY

SURVEYOR'S OFFICE 1965 T255

R4W S.E. D.L.C. 49 — " & MK new
BTs —

31" cedar N. 80° W. 38° ft.

Mkd. " S.E. D.L.C. 49 CS BT "


This tree is most southerly of a group
of 3 from one trunk.

6" D. FIR N. 40° W. 35° ft.

Mkd " S.E. D.L.C. 49 CS BT "

JAN. 27, 1965

U.R.T.
M.D.
J.B.



C. S. File No. 53/47-3