

517/516
Renew Sec. Cor. 520/521 T255 R4W

Fd. at Cor. 3/4" x 38" I.P. ^{-RAN #23} out of ground

& out of place. Fd. no trace of BLM.

BRASS Cap set in 1957. BT's as follows-

5" Now 8" FIR N. 62° E. 27 1/2 ft.

BT Turned out & lying face down.

5" Now 10" FIR S. 15 1/2° E. 23 1/2 ft.

alive & Healed over - we do not open

15" Now 17" FIR S. 41 1/2° W. 87 1/2 ft.

Alive - Healed over - we do not open.

16" Now 18" cedar N. 46° 45' W. 91 1/2 ft.

Now 8' hi snag - T255 R4W 517 BT "GCA 16

Visible on partially grown over face.

We set new 1" I.P. & BRASS Cap MKd

"COUNTY SURVEYOR'S OFFICE 1965

T255 R4W ^{517/516}/_{520/521}" & set I.P. along

side. MARK NEW BT-

6" D. FIR N. 30° E. 15° ft.

Mkd "T255 R4W 516 CS BT"

No Tree suitable to N.W.

Feb. 2, 1965

V.R.T.
M.D.
J.B.

~~W. R. T. J. B.~~