

Renew N.E. DLC #49 T255 R4W. Ren #55

Fd. of cor. $1\frac{1}{4}$ " AXLE & following BTs-

28" W. o2K S. 61° W. $61^{\frac{1}{2}}$ ft

Shows SCAR. Tree was used as 9th post

8" FIR N. 34° W. $68^{\frac{1}{2}}$ ft.

Now STUMP.

12" B. OAK (STUMP) N. 6° W. $21^{\frac{1}{2}}$ ft.

Old o2K (SNAG) N. 4° W. $79^{\frac{1}{2}}$ ft

Badly Burned. We set 1" I.P. & BRASS
CAP FOR WITNESS CORNER 20° ft North
of axle MKD" COUNTY SURVEYOR'S OFFICE

1964 T255 R4W W.C. 20 FT. S. TO

N.E. DLC 49 7" & MK New BT.

21" W. o2K S. 53° W. $94^{\frac{1}{2}}$ ft.

MKD" W.C. N.E. DLC 49 CS BT"

No other Trees close.

This cor. lies S. 5° ft of

fence bearing S. 70° W. The
stump of Evans' B. oak bears

N. 70° W. $2^{\frac{1}{2}}$ ft. We Drive AXE

Flush with ground.

U.R.T.

Oct. 30, 1964

M.D.

J.B.

W.R. Tracy

(#79)
+X✓

C.S. File No. 5347-55