


✓ AT OUR RENEWAL OF FLESER'S
RENEWAL OF S.E. COR. D.L.C. 51
REMOVE BRASS CAP SET PREVIOUSLY
4 REPLACE IT WITH $\frac{3}{4}$ " IRON ROD.
CHANGE MARKINGS ON B.T.'S MKD.
EARLIER TO READ "R.P.C.S BT"

△ HUB 115



SET BRASS CAP MKD. "COUNTY
SURVEYOR'S OFFICE 1964 T26S R5W
S.E. D.L.C. 51]"

BLAZE & SCRIBE NEW TREES:

12" WHITE OAK $N 61 \frac{1}{2}^\circ E$ 8⁷ FT.

MKD. "SE D.L.C. 51 CS BT"

15" DOUG. FIR $S 84^\circ W$ 58² FT.

MKD. "SE D.L.C. 51 CS BT"

✓ - CALCULATED POSITION FROM SURVEY

NO OLD B.T.'S FD.

C553/51-11