

Renewal

$\frac{1}{2}$

7325 R5 W

Found

EO D. Pin Now 24" stump South 90° E
opened for Service 12"
EO Dist to Face

P. F. V Now 39" S58E 123°
Spawns good Seal Dist. to Face

Also 1/2" I.P.P. 1 foot under ground
and wooden stake scribed
C.C. 1/5 2 C.S.

Renewal

Set Brass cap at 1/4 corner MATR
County Surveyors office

7325 R5 W

$\frac{1}{4}$ $\frac{1}{2}$

285 R5 W

1967

New Bearing Tree

8" Laurel S 69° W 15° E
scribed 1/5 2 C.S. ST

Note: This cap lies at corner,
cap bearing South + East

Renewal #3

8-10-67

1967
12/14
1968

73-133-5

164

O.V. J.W.D.

C.S. File No.

53/5213

DIETZGEN NO. 385-B