

Renewal

28/37
33/34

T325 R5W

Found:

ORT's
18" D. Fir NW 22" N 29 E 71 E
Faint Bark scribble "S" "W" "17"

20' lateral NW corner S 57 E 12 S
Strike marks visible but not legible

40" D. Fir NW 98" N 10 W 25 E
Faint Bark scribble "S"

No trace of SW RT

Renewal

Set Brass cap at Sec cor MAD
county surveyors office

T325 R5W

528/527
535/534

1967

New Bearing Trees

11" D. Fir S 48 E 27 E
Scribbled T325 R5W S 39 CS RT

40" D. Fir stump S 27 W 31 E
Scribbled T325 R5W S 33 CS RT

15" Cedar N 81 W 49 E
Scribbled T325 R5W S 28 CS RT

7-1-67
~~T325~~
~~R5W~~
J.C.S.

951

O.N. J.W.B.

C.S. File No

53/52-35

DIETZGEN NO. 3886-6