

Renewal

27/26  
29/35

T325 R5W

Found

29" Fir saw 271 S57 1/2 W 109 E  
Shows good saw

28" Pine saw 2nd N 42 W 51 E  
Strike visible "327" 85"

12" E Pipe at sec. cor.

Renewal

New Bearing Trees

10" Pine N 21 1/2 W 35 E  
Scribed T325 R5W 527 cor RT

12" Pine N 33 E 43 E  
Scribed T325 R5W 526 cor RT

8" D. Fir S 50 1/2 E 108 E  
Scribed T325 R5W 535 cor RT

Notes:

This cor line 150' west of  
Quinn creek Rd. Also 1 1/2 North of  
E-W Fence line

Renewal #34

7-5-57

~~CS~~  
CS

O.K. J.W.D.

C.S. File No.

53/52-31

DIETZGEN NO. 3885-B