

Renew

$\frac{5}{30}$   
 $\frac{5}{29}$

T30S R9W

Found:

14 x 12 x 10 Stone MAR  $\frac{1}{4}$

6" Hard lock NOW 14" S 35  $\frac{1}{2}$  E 12 1/2

Tree opened showing  $\frac{1}{4}$  Scribe

10" Chingvadin N 49 E 25 1/2

No Trace of this tree

Renewed:

Set Brass cap at  $\frac{1}{4}$  cor. MAR

County Surveyors office 1965  
T30S R9W

$\frac{1}{4}$   $\frac{5}{20}$   
 $\frac{5}{29}$

New Bearing Trees:

18" Chingvadin S 78 W 21 1/2  
Scribed  $\frac{1}{4}$  S 2 CS BT

10" Douglas Fir N 89 E 11 1/2  
Scribed  $\frac{1}{4}$  S 2 CS BT

This cor is about 100' off top  
of ridge

Oct. 11 1965

J.M.G.  
J.C.B.

~~0-269~~

C.S. File No. 53/5365

DIETZGEN NO. 385-6