

Renew

S30 | S29

T30S R9W

S31 | S32

Found:

Broken Stone at Sec. cor.

16" Hemlock N77³/₄ E 50¹/₂ 1/15
Rotten Stump

6" Cedar Now 16" S32¹/₂ W 7/15
open + found scribe "90 S"

18" cedar Now 39" S79¹/₂ E 7/15
Shows good scar

14" Cedar Now 23" N19¹/₂ W 3/8 1/15
Shows good scar

Renewal:

Set Brass cap at Sec. cor. M.R.

County Surveyors Office
T30S R9W

S30 | S29
S31 | S32

1965

New B.T.S.

17" Cedar S73 W 4 1/4
Scribed. T30S R9W S31 CS BT

42" Hemlock N72 E 50 0
Scribed. T30S R9W S29 CS BT

Nov 1, 1965

[Handwritten signature]

+76
+XO

C.S. File No. 53/53-12

DIETZGEN NO. 388-6