

Renewed

$\frac{1}{4}$ S18
 $\frac{1}{4}$ S19

7305-9W

Found:

Iron Pin at $\frac{1}{4}$ cor.

20" cedar stump N 37 $\frac{1}{2}$ E 11 $\frac{5}{8}$
Scribed: " $\frac{1}{4}$ S"

10" W. Fir stump S 1 E 12 $\frac{3}{8}$
Stump completely rotten.

Renewed:

Set Brass Cap at $\frac{1}{4}$ cor. MTD.

County Surveyors office
7305 R 9 W

$\frac{1}{4}$ S18
 $\frac{1}{4}$ S19

1965

DIETZGEN NO. 385-6

NEW Bearing Trees:

6" cedar N 22 E 12 $\frac{7}{8}$
Scribed. $\frac{1}{4}$ S18 CS BT

8" laurel S 3 E 21 $\frac{1}{4}$
Scribed. $\frac{1}{4}$ S19 CS BT

This cor. is located about 150 $^{\circ}$
from top of ridge, on the West
slope.

11-18-65

J. M. J.

J. C. B.

J. M. J.

C. S. File No. 53/53-18