

Renewal R 513 518 R T30S

10
W 524 519 W

Found

40" Douglas Fir now 53" S 85 1/2 W 129 3/4

Tree had been opened & badly
burned.
Reopened stump for scribbing 5"

No Trace of Mound of Rock,
or Stone

Renewed:

Set Brass cap set Sec. Cor. M.K.P.
County Surveyors office

T30S

R 513 518 R
10
W 524 519 W

19 65

DIETZGEN NO. 385-6

New Bearing Trees:

17" Douglas Fir N 47 E 14 0
T30S R 9 W S 18 CS BT

19" Douglas Fir N 38 W 16 2
T30S R 10 W S 13 CS BT

19" Cedar S 48 W 7 0
T30S R 10 W S 24 CS BT

6" Hemlock S 7 E 13 0
R 9 W S 19 CS BT

Cap is about 20" North of Rock Bluff.

+ #87

C. S. File No. 53/53-73

N-15-65
J. W. S.
C. S.
S. W. G.