

Renewal S 26 T 30 S 59 W
 S 1 T 31 S 59 W

Found:

10" Douglas Fir N 10 W 33

This tree down + rotten

21" Douglas Fir S 85 E 26

This tree down + rotten
 open tree for scribe "BT" found

Renewed:

Set Brass cap at $\frac{1}{4}$ cor. McO
 County Surveyors office

T 30 S
 S 26 P
 S 1 P
 T 31 S W
 1965

DIETZGEN NO. 385-6

New Bearing Trees:

8" Cedar N 13 E 27

scribed T 30 S P 9 W S 53 E C S BT

5" Douglas Fir S 37 W 72

scribed S 1 C S BT

This cor. is located in bottom of
 small Ravine

#87-130
 + X #27-731

11-5-65
 J. M. G.

C. S. File No. 53/53 J. C. G.