

Renew Sec. Cor.  $\frac{526}{535} | \frac{525}{536}$  T305 R9W

Fd. st. Cor. 3 old BT's & Rotted Remains  
of other BT. - & Cor. Stone.

18" Now 42" cedar N  $1^{\circ}$  W. 160  $\frac{1}{2}$  ft.  
Shows Scar.

12" Fir S,  $20^{\circ}$  W 132 ft - down &  
very Badly Rotted.

20" Now 36" N,  $41\frac{1}{2}^{\circ}$  E 168 ft.

We open & Find "B" Scribe.

36" Now 40" Pine S,  $59^{\circ}$  E. 114  $\frac{1}{2}$  ft.

Shows Scar. Set 1" I.P. at Cor  
with Rock along side. & Brass Cap MKd. \*

COUNTY SURVEYOR'S OFFICE 1964

T305 R9W  $\frac{526}{535} | \frac{525}{536}$  " & MKd. New BT's -

9" D. Fir S,  $45^{\circ}$  E. 25  $\frac{1}{2}$  ft.

Mkd. " T305 R9W S 36 CS BT "

8" D. Fir South 143 ft.

Mkd. " T305 R9W S 35 CS BT "

13" D. Fir N,  $19^{\circ}$  W, 20  $\frac{1}{2}$  ft.

Mkd. " T305 R9W S 26 CS BT "

15" D. Fir N,  $70^{\circ}$  E. 23  $\frac{1}{2}$  ft.

Mkd. T 305 R9W S 25 CS BT "

Oct. 2, 1964

+ X ✓

~~J. A. Tracy~~

K.R.T.  
M.D.  
B.S.  
M.S.  
J.B.

C. S. File No.  $\frac{53}{53}$  - 44