

Review $\frac{1}{4}$ $\frac{516}{521}$ T305 R9W

Fd. at Cor. a Rock 12" x 10" x 10" in
place with " $\frac{1}{4}$ " on North face & a
6" Now 14" D. FIR S. $57\frac{3}{4}^{\circ}$ E. 16 $\frac{1}{2}$ ft.

We open & find " $\frac{1}{4}$ " scribe. No
Trace of other BT. Set 1" I.P.
& Brass Cap in place of Rock & set
Rock along side. Brass Cap MKd

"COUNTY SURVEYOR'S OFFICE 1964
T305 R9W $\frac{1}{4}$ $\frac{516}{521}$ " & MK New
BT's -

30" D. FIR S. 77° E. 32 $\frac{3}{4}$ ft.

Mkd " $\frac{1}{4}$ S 21 CS BT."

20" D. FIR N. 42° W. 65 $\frac{1}{2}$ ft.

Mkd " $\frac{1}{4}$ S 16 CS BT"

This cor lies on steep
south slope approx. 100° North
of creek.

Oct. 9, 1964

V.R.T.
M.D.
J.B.

~~A. R. Tracy~~

+XO

C. S. File No. 53/53 - 49