

Renewal  $\frac{1}{4}$  S14 T30S R9W

Ed. of Cor., Trees Recorded in Renewal  
#18. Using the Recorded Bearings

we cannot bring distances to  
intersection. We set 1" I.P. &

BRASS cap of proper bearings to  
BTs & Take new Level distances.

BRASS Cap MKd. "COUNTY SURVEYORS'  
OFFICE 1964 T30S R9W  $\frac{1}{4}$  S14 T30S

Existing BTs as follows -

7" D. FIR N. 73° W. 86<sup>s</sup>

20" Cedar N. 73° E. 116<sup>e</sup>

This Cor. Lies on West side  
of New 12 mile Creek Road.

Oct. 7, 1964

U.R.T.  
M.D.  
J.B.

~~U. R. Tracy~~

TXO

C. S. File No. 53/53-67