

36/51

T205

Renewal

T215 R10-9W

Found:

16" Cedar N10W 27" N66SE 17"

shows good scar

16" Cedar N0W 19" N157W 34"

Scrub visible "5"

Also Brass cap at Sec cor MAP

General land area

T205

R10W R9W

536 531

T215 R10W S1

1951

Renewal

New Bearing Tree

29" Maple S27E 29"

Scrubbed T215 R10W S1 CS ST

Also Tagged other RTs.

9-30-69

~~Handwritten scribbles~~

D.M.'s
S.D.

*37-T20-10

*31-T21-10

*16-T20-9

*6-T21-9

C. S. File No. 53/66-17

DIETZGEN NO. 385-6